



महाराष्ट्र शास

सार्वजनिक बांधकाम विभाग, बुलडाणा

कार्यकारी अभियंता यांचे कार्यालय, एस.टी. बस स्टँडच्या बाजूला, बुलडाणा - ४४३००१

IN THE SERVICE OF NATION

दूरध्वनीक्रमांक :- ०७६२-२४२३९८

Website:- www.mahapwd.com

Mail:- buldhana.ec @mahapwd.com

buldhana.ec@mahapwd.gov.in

जा.क्र.साबांबु/चिशा /4252/ २०२५

दिनांक : 27/06/ २०२५


प्रति,

प्राचार्य,  
शिवसाई युनिव्हर्सल ज्ञानपीठ,  
अजिंठा रोड, कोलवड बुलडाणा.

विषय :- ईमारत सुरक्षा प्रमाणपत्राबाबत...

- संदर्भ :- १. आपला दि. २४.०६.२०२५ रोजीचा अर्ज.  
२. उपविभागीय अभियंता सा.बां. उपविभाग बुलडाणा हयांचे पत्र क्र. ७३७/तां/२०२५ दि.२६.०६.२०२५

उपरोक्त विषयांकित संदर्भ क्र. १ नुसार शिवसाई युनिव्हर्सल ज्ञानपीठ अजिंठा रोड, कोलवड, बुलडाणा यांच्या ईमारत सुरक्षा प्रमाणपत्राबाबत अर्ज या कार्यालयात प्राप्त झाला होता. त्या अनुषंगाने संदर्भ क्र. २ नुसार उपअभियंता सार्वजनिक बांधकाम उपविभाग बुलडाणा यांच्या अहवालानुसार प्राचार्य शिवसाई युनिव्हर्सल, अजिंठा रोड बुलडाणा हयांना ईमारत सुरक्षा प्रमाणपत्र देण्यात येत आहे.

  
कार्यकारी अभियंता,  
सार्वजनिक बांधकाम विभाग  
बुलडाणा.

प्रतिलिपी — उपविभागीय अभियंता सार्वजनिक बांधकाम उपविभाग बुलडाणा यांना माहीतीसाठी प्रत रवाना.

## BUILDING SAFETY CERTIFICATE

APPENDIX -XI

No.

Dated:

Certified that the existing building SHIVSAI UNIVERSAL DNYANPEETH at AJINTIA ROAD, KOLWAD, BULDHANA comprised of Ground Floor basement(n) and First Floor, Second Floor (upper floors) owned/occupied by SHIVSAI UNIVERSAL DNYANPEETH at AJINTIA ROAD, KOLWAD, BULDHANA Run by NAVJYOT SHIKSHAN PRASARAK MANDAL LAVHALA, TA.MEHAKAR DIST.BULDHANA. have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of Public Work Department on date 23-06-2025 in the presence of PRAMOD PARSHURAM MOHARKAR, PRINCIPAL and that the building/premises is fit for occupancy up to classes X (X/ XII) with effect from 2025-26 for a period of 1 (one) years in accordance with rule and subject to compliance of the specific conditions as appended.

1. Structural Stability should be examined also with reference to location, altitude, intensity of wind floor.
2. Fire safety inspection/ report should be done by agency separately.

Issued on 26-06-2025 at Buldhana by

\*Strike out whichever is not applicable.

Signature with Seal:


Name:

Designation:

Name Address of Department/ Office:

(Assistant Engineer & above officer of concerned Govt. Department only)

  
Sub Divisional Engineer  
P.W.Sub-Division, Buldana

  
Executive Engineer  
Public Works Division  
Buldhana

Note: This certificate should be signed / issued by Assistant Engineer & above officer of concerned Govt. Department only